




LASER MARKING THE BLOCK

1

2



REVISIONS				
REV	DESCRIPTION	REL	DATE	APPROVED
A	INITIAL RELEASE	P.T	7-6-09	
B	REVISED(ADD LASER MARKING)	P.T	10-29-09	



- 1) PUT THE ZIP LOCK BAG BETWEEN THE TWO PACKING SPONGE. 10 PCS IN EACH BOX.
- 2) FIX A LABEL ON THE PACKING BOX AFTER MARK THE LABEL AS SHOWN.
- 3) TEXT SIZE: 3mm HIGH X 100% (<#2 STANDARD WIDTH>) WIDE.

ITEM	P/N	DESCRIPTION	QTY
1	AC-D03326	TRIAIX MOUNTING BLOCK	1
2	1004174-5	BAG, ZIP LOCK, 3x4"	1
3	ENR-2PCK-014A	BOX BIG	0.1
4	ENR-2PCK-016A	PACKING SPONGE BLACK	0.2
5	AC-H02056	1-1/7" X 3-1/2" LABEL	0.1

UNLESS OTHERWISE SPECIFIED: ALL DIMENSIONS ON THIS DRAWING ARE IN INCHES AND THUS SHALL BE INTERPRETED PER ANSI Y14.5M-1994. TOLERANCES ARE AS FOLLOWS: FRACTIONS DECIMALS ANGLES		THIRD ANGLE PROJECTION		measurement SPECIALTIES	
± .xx ±	± .xxx ±	APPROVALS	DATE	TITLE	
MATERIAL:		DRAWN	7-6-09	64C TRIAXIAL	
FINISH		CHECKED	7-6-09	MOUNTING BLOCK PACK	
		APPROVED		SIZE CAGE NO DWG NO	
				B AC-A03272	
				SCALE SHEET 1 OF 1	

PUT TRIAX MOUNTING BLOCK INTO A
ZIP LOCK BAG.

MODEL 64C	USED ON	NEXT ASSY
-----------	---------	-----------